BVA

## EXISTING CONDTIONS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

ALEXANDRIA
Jones Point Light House
Fox Ferry
Norfolk Slip
Barge Slip
Alexandria Marine Railway
Shipbuilding Slip
Hunting Creek
Oliver Pullman Est.
John Linn. 16a.
E. Grayson. 10a.
C. Johnson 26a.
Henry Johnson
Coleman Swift & Hargrave
Shipstone Works
Gibbons Rancher Yard
Alexandria Water Works Reservoir
Shuters Hill
Washington
Columbia Av.
Spring Park
Pitt
Fairfax
Royal
Union
Water
Lee
Church
Duke
Queen
Princess
Oronoco
Pendleton
Wilkes
Prince
Gibbon
Franklin
Madison
Jefferson
Green
Potomac
Columbus
Washington
Patrick
Alfred
West
Fayette
Payne
Pitt
Lee
Union
Water
Fairfax
Royal
Church
Duke
Queen
Princess
Oronoco
Pendleton
Wilkes
Prince
Gibbon
Franklin
Madison
Jefferson
Green
Potomac
Columbus
Washington
Patrick
Alfred
West
Fayette
Payne


1st Story of Banking House — Alexandria D.C.
— as it now is.
Lot 123.5
Stables
16.6
3.6
Privies
6.6
8.6
Yard
25.0
Sinking of
4 or 5 feet
12.0
9.6
Alley — 5½ ft. wide
Pump
Vault
10×17
Vault
10×17
Banking Room
25½ × 36
Fairfax St.
Stairs
6.0
Alley
10.0
10×19.5
12.9×15
19.6×16.6
Stairs
Stairs
13.0
9.0
Cameron Street
REPRODUCED FROM HOLDINGS OF THE NATIONAL ARCHIVES

BRADDOCK HOUSE, ca 1910-1920

PROJECT INTRODUCTION

BRADDOCK HOUSE, ca 1958

PROJECT INTRODUCTION

BVA

POST HOTEL DEMOLITION

PROJECT INTRODUCTION

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

POST HOTEL RESTORATION, ca 1973

PROJECT INTRODUCTION

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023



BVA

## HISTORIC CONDTITION
## WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023



BVA

# WINDOW SHUTTERS

## HISTORIC ARCHITECTURAL ELEMENTS

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023





BVA

## HISTORIC CONDTITION

## WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

CleanHarbors
NOTICE






BVA

## WATERPROOFING AND NEW LINTELS
## WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023



NOTICE
ATTENTION

FLAT OUT BEST
LIFETIME

BVA

LINTEL INSTALL

WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

LINTEL INSTALL

WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

LINTEL INSTALL

WINDOW REPAIR

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023




BVA

# WINDOW DETAILS

## RACOON-ING WINDOWS

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023


NEW STONE SILL
SILL FLASHING W/ COTTON ROPE WEEPS
2X BACK DAMN, COATED 6-SIDES W/ LIQUID APPLIED WATERPROOFING MEMBRANE
LIQUID APPLIED WATERPROOFING MEMBRANE
FILL CAVITY W/ INSULATION

BVA

## EXISTING CONDTIONS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## EXISTING CONDTIONS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## CONDITION BENEATH STUCCO

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## CONDITION BENEATH STUCCO

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023


AQUIA CREEK
ORIGINAL
BRIAR HILL
REPLACEMENT
≠ INDIANA LIMESTONE
FLOOR.
Family Room
HARDWOOD
FLOOR.



BVA

## EXISTING CONDTIONS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023





BVA

## HISTORIC PROFILE

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023






BVA

## FOUND CONDITION AT BRICK MASONRY BEARING ON STONE MASONRY WALL
## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023




## GENERAL OUTLINE OF FORCES ON LOWER WALL AREA
## STONE WATERTABLE




BVA

## STRATEGY CONSIDERED AND REJECTED - FULL BLOCK REPLACEMENT

### STONE WATERTABLE

bsc SCXXV 25 Years of Excellence




BVA

## STRATEGY ADOPTED - MINIMUM EXISTING STONE REMOVAL

### STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023




1 S800 **WEST ELEVATION**
SCALE: 1/2" = 1'-0"




2 S800 **PARTIAL NORTH ELEVATION**
SCALE: 1/2" = 1'-0"




3 S800 **PARTIAL NORTH ELEVATION**
SCALE: 1/2" = 1'-0"

BACKGROUND DRAWINGS CREATED BY BOATMAN AND MAGNANI INC. 2023-02-06




1 S850 TYP. WINDOW OPENING SECTION DETAIL
SCALE: 1 1/2" = 1'-0"




2 S850 TYP. WINDOW JAMB DETAIL
SCALE: 1 1/2" = 1'-0"




3 S850 TYP. WINDOW SILL PLAN DETAIL
SCALE: 1 1/2" = 1'-0"




4 S850 TYP. STONE WATERTABLE REPAIR DETAIL
SCALE: 1 1/2" = 1'-0"




5 S850 TYP. ANCHOR DETAIL
SCALE: 3" = 1'-0"

STONE VENEER ANCHORAGE NOTES:

1. ¾" PINS SHALL GENERALLY BE CENTERED IN THE THICKNESS OF THE VENEER. PINS SHALL BE LOCATED 1½" MINIMUM FROM ANY OTHER EDGE OF THE VENEER STONE. SET PINS IN LATICRETE 254 PLATINUM THINSET OR SIMILAR.
2. PINS LOCATED IN BED JOINTS SHALL BE POSITIONED BETWEEN ⅛ AND ¼ OF THE STONE PANEL LENGTH FROM EACH END OF THE VENEER PANEL. COORDINATE ANCHOR POSITIONS WITH STONES ABOVE AND BELOW.
3. ALL CLIPS, PINS, PLATES AND FASTENERS SHALL BE STAINLESS STEEL.
4. ¼" TAPCON ANCHORS SHALL BE LOCATED 1½" FROM EXISTING STONE JOINTS, AND 2" FROM EXISTING STONE EDGES. SEE DETAILS FOR MORE INFORMATION AND GENERAL ACCEPTABLE CONFIGURATIONS.
5. SEE ARCH FOR DETAILS RELATED TO WATER MANAGEMENT (WATERPROOFING, WEEPS, ETC.).
6. ALL UNEVEN SURFACES SHALL BE PREPARED PLUMB/LEVEL/SQUARE TO RECEIVE THE ANCHORAGE CONDITIONS SHOWN IN THESE DRAWINGS. SHIMMING UP TO ⅜" IS ACCEPTABLE FOR THE TYPICAL CONDITION. SHIMS THICKER THAN ⅜" WILL REQUIRE LONGER TAPCON ANCHORS. THE MINIMUM EMBEDMENT OF THE TAPCON ANCHOR INTO THE SANDSTONE REMNANT IS 2".
7. WHERE EPOXY IS SPECIFIED AT ROD/PIN TO STONE CONNECTIONS PROVIDE DOO ANCHOR-FIX 2001.
8. PROVIDE SOFT JOINTS WHERE NOTED. TYPICALLY SOFT JOINTS SHALL BE PROVIDED BELOW THE ENTIRE LENGTH OF THE CAPPING STONE, AT ALL HEAD JOINTS OF THE CAPPING STONE, AND AT SPECIFICALLY LOCATIONS AT THE BASE OF WALL ADJACENT TO OPENINGS (SEPARATE MARKUP TO BE PROVIDED).




6 S850 STONE WATERTABLE REPAIR DETAIL
SCALE: 1 1/2" = 1'-0"




7 S850 ANCHOR DETAIL
SCALE: 3" = 1'-0"




PLAN DETAIL AT CORNERS WITH LONG LEG 12" AND GREATER IN OVERALL WIDTH
8 S850
SCALE: 3" = 1'-0"




PLAN DETAIL AT CORNERS WITH LONG LEG LESS THAN 12" IN OVERALL WIDTH
9 S850
SCALE: 3" = 1'-0"




1 S850 TYP. WINDOW OPENING SECTION DETAIL
SCALE: 1 1/2" = 1'-0"




SCALE: 3" – 1'-0"




4 S850 TYP. STONE WATERTABLE REPAIR DETAIL
SCALE: 1 1/2" = 1'-0"

BVA

# DETAILS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023




1 S851 STAIR DETAIL
SCALE: 1 1/2" = 1'-0"




2 S851 HEADER STONE ANCHOR DETAIL ADJACENT TO OPENINGS
SCALE: 3" = 1'-0"







3 S851 STEEL BEARING ALTERNATE DETAIL
SCALE: 3" = 1'-0"




4 S851 HEAD SUPPORT WHERE INTERIOR REINFORCING CHANNEL CANNOT BE INSTALLED
SCALE: 3" = 1'-0"

STONE VENEER ANCHORAGE NOTES:

1. ¼" PINS SHALL GENERALLY BE CENTERED IN THE THICKNESS OF THE VENEER. PINS SHALL BE LOCATED 1¼" MINIMUM FROM ANY OTHER EDGE OF THE VENEER STONE. SET PINS IN LATICRETE 254 PLATINUM THINSET OR SIMILAR.
2. PINS LOCATED IN BED JOINTS SHALL BE POSITIONED BETWEEN ⅛ AND ¼ OF THE STONE PANEL LENGTH FROM EACH END OF THE VENEER PANEL. COORDINATE ANCHOR POSITIONS WITH STONES ABOVE AND BELOW.
3. ALL CLIPS, PINS, PLATES AND FASTENERS SHALL BE STAINLESS STEEL.
4. ¼" TAPCON ANCHORS SHALL BE LOCATED 1½" FROM EXISTING STONE JOINTS, AND 2" FROM EXISTING STONE EDGES. SEE DETAILS FOR MORE INFORMATION AND GENERAL ACCEPTABLE CONFIGURATIONS.
5. SEE ARCH FOR DETAILS RELATED TO WATER MANAGEMENT (WATERPROOFING, WEEPS, ETC.)
6. ALL UNEVEN SURFACES SHALL BE PREPARED PLUMB/LEVEL/SQUARE TO RECEIVE THE ANCHORAGE CONDITIONS SHOWN IN THESE DRAWINGS. SHIMMING UP TO ¼" IS ACCEPTABLE FOR THE TYPICAL CONDITION. SHIMS THICKER THAN ¼" WILL REQUIRE LONGER TAPCON ANCHORS. THE MINIMUM EMBEDMENT OF THE TAPCON ANCHOR INTO THE SANDSTONE REMNANT IS 2".
7. WHERE EPOXY IS SPECIFIED AT ROD/PIN TO STONE CONNECTIONS PROVIDE SIKA ANCHOR-FIX-3001.
8. PROVIDE SOFT JOINTS WHERE NOTED. TYPICALLY SOFT JOINTS SHALL BE PROVIDED BELOW THE ENTIRE LENGTH OF THE CAPPING STONE, AT ALL HEAD JOINTS OF THE CAPPING STONE, AND AT SPECIFICALLY LOCATIONS AT THE BASE OF WALL ADJACENT TO OPENINGS (SEPARATE MARKUP TO BE PROVIDED).


MULTI-WYTHE MASONRY WALL
REMNANT STONE
ASHLAR MASONRY REMOVED
IRON CLAMPS NOT REMOVED
FACE OF REMNANT WALL SET BY CLAMPS, STRUCTURAL CALCS, & HISTORIC/ARCH'L FACTORS


MULTI-WYTHE MASONRY WALL
NEW CUBIC WATER TABLE CAP STONE MORTARE DIRECTLY TO REMNANT STONE & SUPPORTED ON REMNANT SHELF
REF: STRUCT'L FOR SUPPORT
SOFT JOINT
NEW VENEER STONE CLIPPED TO REMNANT STONE W/ DRAINAGE PLANE
FACE OF REMNANT WALL SET BY CLAMPS, STRUCTURAL CALCS, & HISTORIC/ARCH'L FACTORS




BVA

# WEEP DETAILS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023




BVA

# WEEP DETAILS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023



BVA

## ORIGINAL STONE EXPOSED

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## SAW DEMO

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023



BVA

## SAW DEMO

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## STONE LEDGE FOR VENEER TO REST ON STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

# WATERPROOFING
## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BV

BVA

WATERPROOFING AND METAL BARS

STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

WATERPROOFING AND METAL BARS

STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

EVOLVE
STONE

BVA

## WATERPROOFING AND METAL BARS

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## DRAINAGE PLANE
## STONE WATERTABLE

bsc SCXXV
25 Years of Excellence

AUGUST 2, 2023

BVA

## DRAINAGE PLANE AND STAIR CONSTRUCTION
## STONE WATERTABLE

bsc SCXXV
25 Years of Excellence

AUGUST 2, 2023

BVA

## STONE INSTALL WITH CLIP SYSTEM
## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## STONE INSTALL WITH CLIP SYSTEM

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

EVOLVE
STONE
SIDE UP

BVA

## STONE INSTALL WITH CLIP SYSTEM

## STONE WATERTABLE

bsc SCXXV 25 Years of Excellence

AUGUST 2, 2023

BVA

## STONE INSTALL WITH CLIP SYSTEM

## STONE WATERTABLE

bsc SCXXV
25 Years of Excellence

AUGUST 2, 2023