












2 of 18





































































































































Duct Leakage Should Be Less Than 5% of Rated Flow As Tested by Pressurization To 25 Pascals

Building Science Corporation

Joseph Lstiburek 63



